

Model Sportage [AL]

Group Fuel System(14)

Number KT2006050901

Subject

Date Thursday, May 11, 2006

## Service Campaign: 1996-2002 Sportage Fuel Tank Inspection (SC059)

Area N. America

### - Description

This bulletin provides information related to a service campaign to inspect the fuel tank on certain 1996 – 2002 Sportage models. This service campaign is in response to an inquiry by the National Highway Traffic Safety Administration (NHTSA) involving possible fuel leakage, mainly in older Sportages.

Campaign

To determine if certain external corrosion or other leakage problems exist in 1996 - 2002 Sportage vehicles, owners of **selected**, **possibly affected Sportages in the Eastern**, **Central and Southern regions** are being notified to bring their vehicle to a Kia dealer for inspection of the fuel tank. As part of this inspection, an inspection sheet must be filled out and returned to KMA for each affected vehicle inspected. (See sample inspection sheet on the last page of this TSB. Once the copies provided have been used you may download the inspection sheet from KGIS, it will be an attachment at the bottom of KGIS screen for Campaign 059)

### - Vehicles Affected

Selected 1996 - 2002 MY Sportage models.

## - Parts Information

| Claim<br>Type | Causal P/N    | Model Year | Production<br>Dates | Qty. | Cond.<br>Code | Cause<br>Code | Repair<br>Description   | Labor Op<br>Code | Time |
|---------------|---------------|------------|---------------------|------|---------------|---------------|-------------------------|------------------|------|
| R             | 0K018 42110C  | 96-00      | All 🛶 1/5/98        | 0    | N99           | C98           | Fuel Tank<br>Inspection | 06001010         | 0.5  |
|               | 0K018 42110D  |            | 1/5/98 - 5/16/00    |      |               |               |                         |                  |      |
|               | 0K018 42110D  | 01-02      | 5/16/00 - 10/1/00   |      |               |               |                         |                  |      |
|               | 0K07A 42110   |            | 10/1/00 - 9/30/02   |      |               |               |                         |                  |      |
|               | 0K011 42110C* | 98-02*     | All -> 9/30/02*     |      |               |               |                         |                  |      |

\* 2 Door Sportage vehicles ONLY.

To improve customer satisfaction always remember to refer to the Warranty Coverage Validations Inquiry screen on your Kia Standard System (KSS) Dealer Menu for a list of additional campaigns that may need to be performed on the vehicle before returning it to the customer.

## - Service Procedure

http://www.kiatechinfo.com/TechInfo/Campaign/print\_preview.asp?docu\_no=240

Use the procedures in this bulletin to inspect possibly affected vehicles and complete the inspection sheet, then fax to Kia Motors America, Attn: D. Bolton at 949-595-5878.

Important:

• The inspection sheet must be completed and returned to KMA before claim for inspection will be accepted. If a fuel tank or other part needs to be replaced, it must be inspected after repair by your DPSM to validate the repair claim.

· Stock of the fuel tanks may be temporarily restricted to ensure adequate inventory.

## A DANGER

Fuel vapors are flammable. Death or serious injury could result if they are ignited. Make sure there are no open flames or smoking in the area of the repair. Adequate ventilation is necessary to prevent a buildup of fumes which could ignite, causing fire or explosion.


Please follow these instructions precisely in carrying out the inspections:

• Fill out the vehicle identification portion of your inspection form.

 Note that this is a purely visual inspection; except as indicated below, no disassembly of any part should be conducted.

#### Location "A" on Inspection Sheet:

Lift up the right rear seat cushion and raise the carpet access section. Loosen and remove the four (4) screws holding the fuel pump cover plate and move plate to the side to obtain access to the area below. Inspect the fuel sending unit area which can be observed through the opening.




1. Look for any of the following conditions and note results on the inspection sheet in Location "A":


- A. Displaced or deteriorated hoses or lines
- B. Cracked or split plastic lines/fittings on the fuel sending unit
- C. Corrosion in the screws which hold the fuel sending unit retaining ring in place such that fuel is leaking past the screw


#### heads

D. Corrosion to fuel sending unit top plate

2. Place vehicle on a lift and raise. Inspect the bottom and sides of the fuel tank and related parts as follows:







11. Note such disruptions on the Inspection Sheet in Location "B" and identify any apparent cause of the coating disruption. Identify whether corrosion is present on the fuel tank and provide a rating for the corrosion level:

A. Corrosion of protective shield's tabs (securing insulator to shield) transferred to tank coating; no disruption

- B. Surface; can be mostly wiped away with a cloth
- C. Superficial; some limited change in the metal surface layer only

http://www.kiatechinfo.com/TechInfo/Campaign/print\_preview.asp?docu\_no=240

- D. Moderate; rust alteration to the metal but no rusting through
- E. Deep corrosion; corroded area may be damp but no indication of fuel escape. Indicate if you can smell fuel
- F. No hole apparent, but fuel is visible
- G. Hole visible



#### Location "C" on Inspection Sheet:

12. Check the seam between the upper and lower halves of the fuel tank for loss of integrity and presence of fuel. If indications of fuel are present, identify apparent cause, such as; cracked or broken weld, impact damage, corrosion, etc., and record on Inspection Sheet

# \*NOTICE

If you identify fuel leakage anywhere on the tank or the fuel pump / sending unit cover, or if conditions E, F or G as described on page 5 (deep corrosion, fuel visible, hole and/or perforation present) are encountered, the <u>appropriate parts</u> <u>must be replaced</u> per instructions on KGIS or in the Service Manual. Contact your DPSM for further warranty claim instructions as required.


13. If no leakage is found, verify the Inspection Sheet is completely filled out. Carefully raise the rear of the protective shield back up to the tank again, and secure to tank with bolt and nut, torque to 18.5 lbs-ft. (25 Nm).

14. Install two bolts securing rear of fuel tank and shield to frame. Tighten and torque to 31-39 lbs-ft. (42-52 Nm). Remove jack stand from fuel tank assembly, and lower vehicle.

15. Inside the vehicle, reinstall the fuel pump unit cover plate, install and tighten 4 screws. Reposition carpet access section and lower seat cushion.

# \*NOTICE

Any parts which are replaced as a result of this service campaign must be held for inspection and photographing by your DPSM. Claims within this campaign will not be paid unless the parts are held and replacement conditions are met.



4/5/06

| Claim<br>Type | Causal P/N    | Model Year | Production<br>Dates | Qty. | Cond.<br>Code | Cause<br>Code | Repair<br>Description   | Labor Op<br>Code | Time |
|---------------|---------------|------------|---------------------|------|---------------|---------------|-------------------------|------------------|------|
| R             | 0K018 42110C  | 96-00      | All 🛶 1/5/98        | 0    | N99           | C98           | Fuel Tank<br>Inspection | 06001010         | 0.5  |
|               | 0K018 42110D  |            | 1/5/98 - 5/16/00    |      |               |               |                         |                  |      |
|               | 0K018 42110D  | 01-02      | 5/16/00 - 10/1/00   |      |               |               |                         |                  |      |
|               | 0K07A 42110   |            | 10/1/00 - 9/30/02   |      |               |               |                         |                  |      |
|               | 0K011 42110C* | 98-02*     | All -> 9/30/02*     |      |               |               |                         |                  |      |

## - Operation Code And Time

\* 2 Door Sportage vehicles ONLY.

To improve customer satisfaction always remember to refer to the Warranty Coverage Validations Inquiry screen on your Kia Standard System (KSS) Dealer Menu for a list of additional campaigns that may need to be performed on the vehicle before returning it to the customer.