

## SAFETY-RELATED VEHICLE RECALLS

Vehicle manufacturers are required to mail a recall notice to all purchasers, owners and dealers when a safety defect or noncompliance with Federal safety standards is found.

This notice identifies the year, make, engine(s) and other information related to the vehicle(s) involved with this recall, along with a brief description of the problem, and other pertinent information. Not all vehicles of a particular year, make and model may be subject to the recall. Contact the manufacturer or one of the manufacturer's dealers with any questions regarding this recall.

### RECALL NOTICE SUMMARY

---

Manufacturer: AMERICAN HONDA MOTOR CO.  
Campaign Number, Case: 04V086000 P23  
Defect Report:  
Recall Initiator: MFR  
Dates: 5/24/2001-12/21/2001  
Date Owner Notified: 4/5/2004  
Vehicles: 2001-2002 HONDA CIVIC, 2000-2002 HONDA INSIGHT  
No. Vehicles Recalled: 2200000  
Noncompliance: ON CERTAIN PASSENGER VEHICLES, THE LOW-BEAM TERMINAL ON THE HEAD LIGHT WIRE HARNESS CAN OVERHEAT AND COULD CAUSE THE LOW BEAMS TO FAIL WITHOUT WARNING.  
Consequence: AN UNEXPECTED LOSS OF LOW BEAMS COULD RESULT IN A CRASH.  
Corrective Action: DEALERS WILL INSPECT THE HEAD LIGHT SWITCH AND COUPLER FOR SIGNS OF HEAT DAMAGE. IF HEAT DAMAGE IS PRESENT, THE DEALER WILL REPLACE THE SWITCH AND COUPLER. IF NO HEAT DAMAGE IS PRESENT, THE DEALER WILL REPLACE THE HEAD LIGHT SWITCH AND ONE MATING PIN IN THE COUPLER. OWNER NOTIFICATION BEGAN ON APRIL 5, 2004. OWNERS SHOULD CONTACT HONDA AT 1-800-999-1009.

---

This recall summary reflects information submitted by the vehicle manufacturer. While it is an accurate reflection of the information submitted, the NHTSA and/or the vehicle manufacturer may make changes at any time. No warranty, expressed or implied, is made as to its accuracy or completeness, nor is any responsibility assumed by Tecfacts Services, LLC. for loss, damages (direct or indirect). consequential or compensatory, including without limitation, lost profits, breaches or defaults caused by reliance on the information in this summary.

Copyright © Tecfacts Services, LLC 2004. All rights reserved. No portion of this document may be reproduced, copied, transmitted, distributed or stored, by any means, in any form electrical or mechanical, including recording or by any information storage or retrieval system without written permission.