

SERVICE BULLETIN ML 0005



Date : Friday, 21 May, 1999
Game : Ripper Ribbit
Subject : Monitor Chassis Fuse

Distribution List

Australasia : - LAI WA, SA, VIC, NSW & QLD - Sales, Operations, Service Departments
- LAI Games, NZ Coin Cascade, webmaster@lai.com.au
Asia : - ML Prod, ML Sales, MGF Operations, MGF Service, Philippines
- LAI Asia Sales, Operations & Service

Problem : The Wells & Gardner Monitor chassis fuse may blow on power up

Cause : The Degauss Coil draws current in excess of fuse rating. This is more likely to happen when the machine is setup to run on a mains voltage of 220 to 250 Volts

Solution : Replace Monitor Chassis Fuse with a 3 Amp delay fuse (Slow Blow).

Note:- A blown monitor chassis fuse may not always be of the above cause. If the fuse glass is blackened and cracked or the recommended replacement blows. Please contact your nearest LAI service center for advise.

Regards

PT Matahari Leisure