

# **SERVICE BULLETIN ML 0012**



Date : 13 September 1999  
Game : Slam'N'Jam ML 000751 to 790  
Subject : Intermittent Connector Problems

---

Distribution List

Australasia : - LAI WA, SA, VIC, NSW & QLD - Sales, Operations, Service Departments  
- LAI Games, info@lai.com.au

Asia : - ML Prod. LAI Asia Sales, Operations & Service

---

**Problem** : Intermittent Connection Problems due to size of Male Connector pins in Connector Housings. This problem is most noticeable on the Front Door, Speaker Pods, Ball gate and Back Board Connectors.

**Solution** : Replace Small Male Connector pins with Molex / Utilux Male Connector Pins. These Pins are available at your closest LAI Games Distributor.

Regards

**Matahari Leisure**