



Technical Service BULLETIN

March 6, 2007

Title: **HVAC ODOR**
Models: '07 Yaris

T S B

HEATING & AIR CONDITIONING
AC001-07

Introduction Some customers may experience an intermittent climate control system odor. An A/C amplifier logic improvement has been made available to decrease odor in the vehicle.

- Applicable Vehicles**
- **2007** model year **Yaris** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Yaris Sedan	JTDBT9#3#7#080862
Yaris Hatchback	JTDJT9#3#7#075526

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	SPECIFICATION	QTY
88650-52291	Same	Amplifier Assembly, Air Conditioner	USA	1
88650-52361	Same		USA Cold Spec	1

Repair Procedure

Remove and replace the A/C amplifier.

Refer to the Technical Information System (TIS), 2007 model year Yaris Repair Manual, *Vehicle Interior - Heating/Air Conditioning - "Air Conditioning: Air Conditioning Amplifier: Removal and Installation"*.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
AC7006	Remove & Replace A/C Amplifier Assembly	0.3	88650-52291	60	02

Applicable Warranty*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

