



Figure 6.14. Stripping multiple seams with open cast method, using one excavating machine. (Top) Casting overburden on first pass. (Bottom) Casting parting on second pass. (After Anon., 1976a. By permission from Bucyrus-Erie Co., South Milwaukee.)