

Keys to Forklift Driving Safety

Avoid tip overs by following these safety rules:



Carry it low

Don't travel with a load raised. Always try to carry loads low.



Don't overload

Be sure to center loads and not overload the forklift.



Keep it slow

Be cautious and slow down when turning corners. Avoid jerking to a start or stop.



Stay inside

Always stay inside the forklift. If you experience a tip over, do not attempt to jump out of the forklift.

