

Beechcraft 35-B33

SB

ECFOK

hours

3599

09/05/01

No	Ver.	Subject	Type	Compliance	Hours	Next inspection	Remaining
2031	II	Shoulder harness	Mandatory	xxxx	xxxx	xxxx	
2045	III	Fuel filler caps	Mandatory				
2109		Fuel system	Mandatory	07/11/97	3131		
2190		Door placards	Mandatory	xxxx	xxxx	xxxx	
2219		Landing gear	Optional	xxxx	xxxx	xxxx	
2242		Flight controls	Mandatory	28/11/00	3599	3624	25
2305		Fuel strainer	Mandatory				
2333	I	Rudder fwr. Spar	Mandatory	05/11/98	3259	3759	160
2360		Wing Forwrd. Spar	Mandatory	05/11/98	3259	3759	160
2363		Door handle	Optional	xxxx	xxxx	xxxx	
2399		Elev. Trim Tab Act.	Mandatory	07/10/98	3234		
2405		Placards	Optional	xxxx	xxxx	xxxx	
2460	I	Flap drive cable	Mandatory	15/12/94	3037	No	
2518	I	Fuel strainer	Mandatory	15/12/94		No	
2527		Control gust lock	Mandatory	xxxx	xxxx	xxxx	
2538	I	Wings inspection	Mandatory	15/12/94	3037	07/11/99 OK, es va fer	
2601		Nose Gear	Optional	xxxx	xxxx	xxxx	
2693		Door handler		07/10/98	3234		
2670		Fuel selector	Mandatory	01/02/99	3269		
3236		Y2K	Recommended	18/05/99	3360	xxxx	
3236	II	Y2K	Recommended				