

*Due to the effects of heat & time, your vehicle's LCD screens may start to fade*



Typical Faulty Screen Appearances



### DISPLAY PROBLEMS ARE COMMON


It's caused by high dashboard temperatures combined with the heat generated by daytime LCD backlight illumination bulbs.

When parked under the sun on a 35°C day with windows closed, your car will experience a dashboard temperature of 60°C.

Starting your car on such a day will turn the LCD backlight illumination on. After 20 minutes (regardless of air conditioner settings) the heat from the illumination bulbs will increase the temperature within the module to over 90°C.

In effect your LCD undergoes accelerated and premature aging.


How to find us in Moorabbin:



**AUTOTRONIC L.C.F.S.  
PTY LTD**

**LIQUID CRYSTAL DISPLAY  
REPAIR SERVICE**

ABN 74 740 626 994

 041 2299 034

Fax (03) 9553 1376

1 Wendy Street  
Moorabbin VIC 3189

**Autotronic LCFS P/L** ABN 74 740 626 994

**Ayhan Boz**

[www.geocities.com/liquidxtal](http://www.geocities.com/liquidxtal)

Automotive industry solutions




0412299034


1 Wendy Street  
Moorabbin Vic 3189



BMW MID Radio display - \$250



Mercedes-Benz W220 S-Class - \$400



Audi A3/A4/A6 - \$250




SAAB SID1/SID2 - \$150

## Common Instruments Serviced



Mercedes-Benz  
W208, W210  
\$200



Ford AU  
Climate Control  
See Detailed Price List



BMW E38, E39 & X5  
\$300

Our satisfied customer base ranges from private owners, fleet operators, automotive electricians, used car dealerships and OEM Factory Service Centers.

## PRICE LIST

Valid from 01.04.2009

Price inc. GST

<b>Ford Climate Control:</b>	<b>\$</b>
Standard Repair (excl. fitting)	90.00
Removal/reinstallation to car	35.00
Illumination bulbs	ea 6.00
Warranty extension to 2 years	25.00
Changeover unit AU1 – Orange LCD	150.00
Changeover unit AU2/3 – Gray LCD	150.00

----

<b>Mercedes-Benz Instrument Cluster:</b>	
Removal/reinstallation to car	35.00

----

<b>BMW Instrument Cluster:</b>	
Removal/reinstallation to car	35.00

Postage & Handling destination dependant

## STANDARD WARRANTY

12 months parts & labour, return to base.