



-102 INSTALLATION
 REPAIR CONFIGURATION & FASTENERS DISTRIBUTION

COMPUTER GENERATED DRAWING - NO MANUAL ALTERATION

QUANTITY REQUIRED				PART NUMBER		DESCRIPTION / SIZE / SPECIFICATION				
DRW	LEYVA	LIMITS UNLESS NOTED	PROJECT	DLR-737-13	TANS			ISSUE	15 OCT 13	REV.
ENG	SAA	FRACTION +/- 1/32	SIZE	A3				SCALE	NTS	INITIAL
APR	TANSPERJ	DECIMAL +/- 1.31%	EQUIP	737				DRAWING NUMBER		
ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE SPECIFIED				TITLE :		UNPRESSURIZED SKIN DENT & PUNCTURE REPAIR, AT BS 1016 & BS 1040 ON T S-12 & S-16 LEFT			DLBR-737-13-11	
APPLICABILITY :						A/C MODEL: BOEING 737-282			SHEET 3 OF 3	
						A/C SERIAL No.: 23842				
						A/C REG. No.: 08-1724				