



Charter Township of Orion

2525 Joslyn • Lake Orion, Michigan 48360 • (248) 391-0304 Fax: (248) 391-9984

Silverbell Oaks H.O.A.
P.O. Box 544
Lake Orion, MI 48361

RE: Cross-Connection Control Program

October 1, 2007

Dear Sir:

An inspection of the drinking or potable water system was made at the lawn irrigation locations at your commercial location. Its uses, relative to possible contamination that could occur due to a backflow or back siphoning of contaminated water were evaluated.

This establishment is **IN COMPLIANCE** with the Charter Township of Orion Codes and Ordinances adopted for the control of backflow and cross-connections in the water system.

State of Michigan Laws (Cross-Connection Rules, Sections 14.6.3 & 14.10) require periodic re-inspections of all facilities and re-testing of Reduced Pressure Backflow Preventers (RPBPs), Double Check Valve Assemblies (DCVAs), and Pressure Vacum Breakers (PVBs) that may be installed on your premises. Re-testing of the devices is required every 5 years and the test reports should be submitted to this office.

If you have any questions, please contact me at 248-391-0304 extension 118.

Sincerely,

Bill Ireland

Bill Ireland, Director
Department of Public Works

Supervisor - Gerald A. Dywasuk

Clerk - Jill D. Bastian

Treasurer - Alice P. Young

Trustees - John Garlicki • Matthew A. Gibb • Michael J. Gingell • John M. Steimel