



2. solder
3. component
4. outline
5. componentmask
6. soldermask
7. plated-drill
8. unplated-drill
9. topsilk
10. bottomsilk
11. toppaste
12. topassembly
13. bottomassembly
14. fab



USB-UART bridge, back (mirrored), scale = 1:1.000
schematics.pcb



USB-UART bridge, front, scale = 1:1.000
schematics.pcb

